

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans
 Run date
 20-Nov-14

 Time
 9:39 AM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 010 Const Calendar Day: 176 Date: 03-Mar-2010 Wednesday Inspector Name: Iranmanesh, Abbas Title: Transportation Engineer

Inspection Type:

Shift Hours: Break: Over Time:

Federal ID: Location:

Reviewer: Liu, Tai-Lin Approved Date: 30-Mar-10 Status: Approved

Weather

Temperature 7 AM 12 PM 4PM Precipitation Condition

Working Day | If no, explain:

Diary:

Work description.

Field Work at Pier 7

Cross Beams CB1, CB2, & CB3

- 1-The cross beams CB3, CB2, and CB1 were inspected thoroughly, the engineers from METS, ABF and CT were present in the inspection process. The following items were observed:
- •The vertical plates of the CBs were not completely straight and they had some misalignment, which might be reduced in the erection process.
- One padeye of the cross beam CB3 had some damages which require correction.

Equipment: Man lift ID# 477-40-5029.

•The CB1 was also inspected; the bottom plate had a dent and a few scratches.

Equipment: Man lift ID# (Not Recorded)

Note: Mike (METS) inspected the top CBs plate.

Lifts 2W & 3W

- 1-Three ABF crews resurfaced the 2W skin plates and stiffeners plate of the face connecting 2W to 1W.
- 2-Two ABF crews transferred the cable trays inside the 2W lift.
- 3-Two ABF crews completed guard railing of 2W.
- 4-It was found that 2 bolts of the T stiffener on W3 line were sheared off while lifting the 3W segment. It is needed to investigate the matter and its effect on the OBG.

Equipment: Man lift ID# 481-93-6009

Crane with ID# Terex RT160.

The hanger used for resurfacing.

NOTE: Victor has been present in the inspection

Office Work

- 1-Working on the excel sheet of the sea fastening of the Lifts 5& 6.
- 2-Continue on the punch list of the items, which need to be checked at the job site.